



Volkswagen Used Car Check Condition Report

This certificate verifies that, at the time the Volkswagen Used Car Check was conducted, the vehicle identified on this Condition Report underwent the checks listed below. This certificate verifies that this vehicle has completed a comprehensive series of tests by a Volkswagen technician. The following Condition Report details the results of 105 points of inspection categorised into: Interior, Exterior, Underbody, Pre-Road Test and Road Test.

Scope of the check



Interior: an inspection of all interior aspects of the vehicle, noting any damage or functionality issues to features such as seatbelts, airbags and locks.



Exterior: an inspection of all exterior aspects of the vehicle, including cosmetic or functional issues with features such as lights, body paint and wheels.



Underbody: involves raising the vehicle on a hoist in order to conduct an inspection of parts including the transmission, suspension and exhaust.



Pre-road test: an inspection of features that are required to make the vehicle operational. It includes tests performed on coolant, oil level and fuel system.



Road test: allows 15-20 minutes for the vehicle to reach operating temperature and includes a performance test on features including the steering wheel, suspension and brakes.

Vehicle details

Polo

70TSI Trendline



Model year
2015



Transmission
7-Speed Auto DSG



Engine
1.0 Litre



Fuel type
Petrol



VIN
WVWZZZAWKU03907



Registration
CA11AA



Odometer (end of check)
112,345km



Car check date
04/01/2021


#	System and features checked	Inspection type	Results	Comments
---	-----------------------------	-----------------	---------	----------


Interior

This category includes a report on all interior aspects of the vehicle, noting any damage or functionality issues to features such as seatbelts, airbags and locks.

001	Keys Remote open/close	Test	<input checked="" type="checkbox"/>	
002	Steering Wheel Adjustment/Lock	Test	<input checked="" type="checkbox"/>	
003	Doors/Handles Function, feel	Test	<input checked="" type="checkbox"/>	
004	Automatic Tailgate Operation Function	Test	<input checked="" type="checkbox"/>	
005	Bluetooth phone system Paired phones deleted	Test	<input checked="" type="checkbox"/>	
006	Warning Chimes Function	Test	<input checked="" type="checkbox"/>	
007	Window Operation Switches, Regulator	Test	<input checked="" type="checkbox"/>	
008	Console Damage	Visual	<input checked="" type="checkbox"/>	
009	Side and Back Windows Chips, Cracks, Leaks	Visual	<input checked="" type="checkbox"/>	
010	Windshields Chips, Cracks, Leaks	Visual	<input checked="" type="checkbox"/>	
011	Seats/Headrests Function, damage	Test	<input checked="" type="checkbox"/>	
012	Seat Heaters Function	Test	<input checked="" type="checkbox"/>	
013	Seat belts/Retractors and Buckles Function, wear	Test	<input checked="" type="checkbox"/>	
014	Air Bags Function, damage	Test	<input checked="" type="checkbox"/>	

#	System and features checked	Inspection type	Results	Comments
015	Mirrors (Interior and Exterior) Function, damage	Test	<input checked="" type="checkbox"/>	
016	Clock Set to correct times	Test	<input checked="" type="checkbox"/>	
017	Glovebox/Ashtray Function, Light, Lock	Visual	<input checked="" type="checkbox"/>	
018	Instrument Lights Function	Visual	<input checked="" type="checkbox"/>	
019	Sunroof Function, Sealing	Test	<input checked="" type="checkbox"/>	
020	Lighter/12V Outlets Function	Test	<input checked="" type="checkbox"/>	
021	Dome, Map, Sun Visor Lights Function	Test	<input checked="" type="checkbox"/>	
022	Door/Child Safety Locks Function	Test	<input checked="" type="checkbox"/>	
023	Alarm System Function	Test	<input checked="" type="checkbox"/>	
024	Upholstery Wear, Damage	Visual	<input checked="" type="checkbox"/>	
025	Carpet/Floor Mats/Boot Wear, Damage	Visual	<input checked="" type="checkbox"/>	
026	Door Panels, Fuel/Boot Release Damage	Visual	<input checked="" type="checkbox"/>	
027	Headliner/Sun Visor Damage	Visual	<input checked="" type="checkbox"/>	
028	Ignition Switch Wear, Damage	Operation	<input checked="" type="checkbox"/>	
029	Ignition Switch All Warning Lights	Turn to "On"	<input checked="" type="checkbox"/>	

#	System and features checked	Inspection type	Results	Comments
 Pre-road test	The pre-road test involves an inspection of features that are required to make the vehicle operational. It includes tests performed on coolant, oil level and fuel system.			
030	Timing Belt Damage, Replacement Interval	Visual	<input checked="" type="checkbox"/>	
031	Cooling System Leaks, Hoses, Radiator-Pumps	Visual	<input checked="" type="checkbox"/>	
032	Coolant Level	Visual	<input checked="" type="checkbox"/>	
033	Coolant Condition	Test	<input checked="" type="checkbox"/>	Protected to temperature: -22 degrees
034	Battery/Charging System Function, Condition	Test	<input checked="" type="checkbox"/>	
035	Battery Cables/Clamps Condition	Visual	<input checked="" type="checkbox"/>	
036	Ignition Leads Condition	Visual	<input checked="" type="checkbox"/>	
037	Electrical System Wire Routing, Connections	Visual	<input checked="" type="checkbox"/>	
038	V-belts Loose, Condition	Visual	<input checked="" type="checkbox"/>	
039	Air Filter Condition	Visual	<input checked="" type="checkbox"/>	
040	A/C Compressor, Clutch Function, Noise	Test	<input checked="" type="checkbox"/>	
041	Cooling Fan Function, Noise	Test	<input checked="" type="checkbox"/>	
042	Washer Reservoir Fluid Level, Leak	Visual	<input checked="" type="checkbox"/>	
043	Engine Oil Level, Condition	Visual	<input checked="" type="checkbox"/>	

#	System and features checked	Inspection type	Results	Comments
044	Power Steering Fluid Level	Visual	<input checked="" type="checkbox"/>	
045	Brake Reservoir Fluid Level	Visual	<input checked="" type="checkbox"/>	
046	Fuel System Leaks, Fittings, Filter	Visual	<input checked="" type="checkbox"/>	
	Exterior	This category includes a report on all exterior aspects of the vehicle, including cosmetic or functional issues with features such as lights, body paint and wheels.		
047	Body and paint (Passenger side) Scratch, Dent, Rust, Marks	Visual	<input checked="" type="checkbox"/>	
048	Body and paint (Driver side) Scratch, Dent, Rust, Marks	Visual	<input checked="" type="checkbox"/>	
049	Body and paint (Rear / Roof / Bonnet) Scratch, Dent, Rust, Marks	Visual	<input checked="" type="checkbox"/>	
050	Turn Signal/Marker Damage, Operation	Visual	<input checked="" type="checkbox"/>	
051	Emergency Flashers Operation	Visual	<input checked="" type="checkbox"/>	
052	Headlights Lens Damage	Visual	<input checked="" type="checkbox"/>	
053	Headlights High/Low Beam	Visual	<input checked="" type="checkbox"/>	
054	Fog Lights Lens Damage, Operation	Visual	<input checked="" type="checkbox"/>	
055	Tail/Brake/Reverse/License Plate Lights Lens Damage, Operation	Visual	<input checked="" type="checkbox"/>	
056	High-Mount Brake Light Operation	Visual	<input checked="" type="checkbox"/>	

#	System and features checked	Inspection type	Results	Comments
057	Sunroof drains Clear and cleaned	Visual	<input checked="" type="checkbox"/>	
058	Tyre mobility Set expiration date	Test	<input checked="" type="checkbox"/>	
059	Cargo Tray Switch function and Light operation	Test	<input checked="" type="checkbox"/>	
060	Boot/Rear Hatch/Trim/Roof Rack Function, Feel, Lights	Test	<input checked="" type="checkbox"/>	
061	Spare Tyre, Jack, Tool Kit Damage, Tyre Pressure	Visual	<input checked="" type="checkbox"/>	
062	Cabriolet Roof Condition, Function	Visual	N/A	

Underbody (Vehicle on hoist)

The underbody test involves raising the vehicle on a hoist in order to conduct an inspection of parts including the transmission, suspension and exhaust.

063	Wheels Damaged, Matched	Visual	<input checked="" type="checkbox"/>	
064	Tyres Damaged, Pressure	Visual	<input checked="" type="checkbox"/>	
065	Tread Depth Condition	Visual	<input checked="" type="checkbox"/>	Tread depth (mm): LF 22 RF 25 RR 24 LR 30
066	Wheel Covers Damage, Missing	Visual	<input checked="" type="checkbox"/>	
067	Transmission Oil Leak	Visual	<input checked="" type="checkbox"/>	
068	Transmission Worn Mounts	Visual	<input checked="" type="checkbox"/>	
069	C/V Joint Boots Leaks, Worn	Visual	<input checked="" type="checkbox"/>	

#	System and features checked	Inspection type	Results	Comments
070	Axles, Suspension Damage	Visual	<input type="checkbox"/>	Condition: Light damage
071	Control Arms, Bushings, etc. Damage	Visual	<input type="checkbox"/>	Condition: Light damage
072	Engine Leaks, Mounts	Visual	<input checked="" type="checkbox"/>	
073	Shock Absorber/Struts/Springs Leaks, Damage, Weak	Visual	<input checked="" type="checkbox"/>	
074	Brake System Damaged, Leaking	Visual	<input checked="" type="checkbox"/>	
075	Brake Pad Lining Thickness	Measure	<input checked="" type="checkbox"/>	Thickness (mm): 13
076	Brake Discs /Callipers Thickness	Visual/Measure	<input checked="" type="checkbox"/>	Thickness (mm): 23
077	Brake Discs /Callipers Leaks, Specs	Visual/Measure	<input checked="" type="checkbox"/>	
078	Exhaust Leaks, Alignment	Visual	<input checked="" type="checkbox"/>	
079	Exhaust Damage, Wear	Visual	<input checked="" type="checkbox"/>	
080	Steering Leaks, Noise	Visual	<input checked="" type="checkbox"/>	
081	Hoses Damaged, Leaks	Visual	<input checked="" type="checkbox"/>	
082	Underbody Other damage, Leaks	Visual	<input checked="" type="checkbox"/>	
083	Rear Final Drive Other damage, Leaks	Visual	<input checked="" type="checkbox"/>	

Road Test

The road test allows 15-20 minutes for the vehicle to reach operating temperature and includes a performance test on features including the steering wheel, suspension and brakes.

Odometer reading at start of road test: **112,340 km**

084	Engine Starting, Performance, Idle, Knock, Vibration, Valve Noise, Smoke	Test	<input checked="" type="checkbox"/>	
085	Automatic Transmission/DSG Performance, Slippage, Noise, Shift points, down shift	Test	<input checked="" type="checkbox"/>	
086	Manual Transmission Performance, Shifting, Noise	Test	<input checked="" type="checkbox"/>	
087	Differential Noise	Test	<input checked="" type="checkbox"/>	
088	Clutch Operation, Slippage, Shudder	Test	<input checked="" type="checkbox"/>	
089	Steering Noise, Effort, Vibration, Pulling	Test	<input checked="" type="checkbox"/>	
090	Steering Wheel Position (straight)	Visual	<input checked="" type="checkbox"/>	
091	Suspension Function, Feel, Noise	Test	<input checked="" type="checkbox"/>	
092	Brakes Function, Feel, Noise	Test	<input checked="" type="checkbox"/>	
093	Parking Brake Function	Test	<input checked="" type="checkbox"/>	
094	A/C System / Defroster Operation, Noise	Test	<input checked="" type="checkbox"/>	
095	Heater Operation, Noise	Test	<input checked="" type="checkbox"/>	
096	Speedometer Function, Noise	Test	<input checked="" type="checkbox"/>	

#	System and features checked	Inspection type	Results	Comments
097	Horn(s) Function	Test	<input checked="" type="checkbox"/>	
098	Radio/Antenna Function/Pre-Sets	Test	<input checked="" type="checkbox"/>	
099	CD/Navigation Function	Test	<input checked="" type="checkbox"/>	
100	Speakers Noise, Vibration	Test	<input checked="" type="checkbox"/>	
101	Wipers/Washers (F and R) Function/Jets Aim	Test	<input checked="" type="checkbox"/>	
102	Wiper Blades/Arms Function, Performance	Test	<input checked="" type="checkbox"/>	
103	Cruise Control Function	Test	<input checked="" type="checkbox"/>	
104	Wind Noise, Squeaks, Rattles / Wheel Bearing or Exhaust Noises Noise, Vibration	Test	<input checked="" type="checkbox"/>	
105	Engine Hot Start/Idle	Test	<input checked="" type="checkbox"/>	

Odometer reading at end of road test: **112,345 km**